

RT 0.5 PRESSURE/TORQUE CONVERSION CHART



RAPID-TORC

PRESSURE IN PSI	FT. LBS.	KGM	NM	PRESSURE IN BAR
1500	55	8	75	104
1600	59	8	80	110
1800	67	9	91	124
2000	75	10	102	138
2200	83	12	113	152
2400	92	13	124	165
2600	100	14	136	179
2800	109	15	147	193
3000	117	16	159	207
3200	125	17	169	220
3400	133	18	180	234
3600	140	19	190	248
3800	148	20	201	262
4000	156	22	211	276
4200	164	23	223	290
4400	172	24	234	303
4600	181	25	245	317
4800	189	26	256	331
5000	197	27	267	345
5200	206	28	279	358
5400	215	30	291	372
5600	223	31	303	386
5800	232	32	315	400
6000	241	33	327	414
6200	249	34	338	427
6400	257	36	349	441
6600	266	37	360	455
6800	274	38	371	468
7000	282	39	382	482
7200	289	40	392	496
7400	296	41	402	510
7600	304	42	412	524
7800	311	43	421	538
8000	318	44	431	552
8200	326	45	442	565
8400	334	46	453	579
8600	342	47	464	593
8800	350	48	474	607
9000	358	50	485	620
9200	366	51	496	634
9400	374	52	506	648
9600	381	53	517	662
9800	389	54	528	676
10000	397	55	538	690

RAPID-TORC
www.rapidtorc.com