

# RT 50 PRESSURE/TORQUE CONVERSION CHART



**RAPID-TORC**

PRESSURE IN PSI	FT.LBS.	KGM	NM	PRESSURE IN BAR
1500	7875	1089	10675	104
1600	8400	1162	11387	110
1800	9450	1307	12810	124
2000	10500	1452	14234	138
2200	11550	1597	15657	152
2400	12600	1743	17081	165
2600	13650	1888	18504	179
2800	14700	2033	19927	193
3000	15750	2178	21351	207
3200	16800	2323	22774	220
3400	17850	2469	24197	234
3600	18900	2614	25621	248
3800	19950	2759	27044	262
4000	21000	2904	28468	276
4200	22050	3050	29891	290
4400	23100	3195	31314	303
4600	24150	3340	32738	317
4800	25200	3485	34161	331
5000	26250	3630	35585	345
5200	27300	3776	37008	358
5400	28350	3921	38431	372
5600	29400	4066	39855	386
5800	30450	4211	41278	400
6000	31500	4356	42701	414
6200	32550	4502	44125	427
6400	33600	4647	45548	441
6600	34650	4792	46972	455
6800	35700	4937	48395	468
7000	36750	5083	49818	482
7200	37800	5228	51242	496
7400	38850	5373	52665	510
7600	39900	5518	54088	524
7800	40950	5663	55512	538
8000	42000	5809	56935	552
8200	43050	5954	58359	565
8400	44100	6099	59782	579
8600	45150	6244	61205	593
8800	46200	6389	62629	607
9000	47250	6535	64052	620
9200	48300	6680	65475	634
9400	49350	6825	66899	648
9600	50400	6970	68322	662
9800	51450	7116	69746	676
10000	52500	7261	71169	690

**RAPID-TORC**  
[www.rapidtorc.com](http://www.rapidtorc.com)