

RTX-14 PRESSURE/TORQUE CONVERSION CHART



RAPID-TORC

PRESSURE IN PSI	FT. LBS.	KGM	NM	PRESSURE IN BAR
1500	2010	278	2725	104
1600	2144	297	2906	110
1800	2412	334	3270	124
2000	2680	371	3633	138
2200	2948	408	3996	152
2400	3216	445	4360	165
2600	3484	482	4723	179
2800	3752	519	5086	193
3000	4020	556	5450	207
3200	4288	593	5813	220
3400	4556	630	6176	234
3600	4824	667	6539	248
3800	5092	704	6903	262
4000	5360	741	7266	276
4200	5628	778	7629	290
4400	5896	815	7993	303
4600	6164	852	8356	317
4800	6432	890	8719	331
5000	6700	927	9083	345
5200	6968	964	9446	358
5400	7236	1001	9809	372
5600	7504	1038	10172	386
5800	7772	1075	10536	400
6000	8040	1112	10899	414
6200	8308	1149	11262	427
6400	8576	1186	11626	441
6600	8844	1223	11989	455
6800	9112	1260	12352	468
7000	9380	1297	12716	482
7200	9648	1334	13079	496
7400	9916	1371	13442	510
7600	10184	1408	13805	524
7800	10452	1446	14169	538
8000	10720	1483	14532	552
8200	10988	1520	14895	565
8400	11256	1557	15259	579
8600	11524	1594	15622	593
8800	11792	1631	15985	607
9000	12060	1668	16349	620
9200	12328	1705	16712	634
9400	12596	1742	17075	648
9600	12864	1779	17438	662
9800	13132	1816	17802	676
10000	13400	1853	18165	690

RAPID-TORC
www.rapidtorc.com